ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00

ROLA CABLU COAXIAL SPACER, RG59, 100m, CCS, Double shielded,1x0.65+32x0.10mm2, CCS+al, Importator: Royal Computers, Bucuresti Str. Culcer Ioan 32, tel: 021.410.21.00